	d States Environmental Pro Washington, D.C. 20						
EPA West							
Water Compliance Inspection Report Section A: National Data System Coding (i.e. PCS)							
Transaction Code NPDE			spection Type	Inspector Fac Type			
1N 25 31 D 0 0 2 0		7 0 6 17	18 C	198 20 1			
21							
	elf-Monitoring Evaluation Rating	BI QA		-Reserved			
67 3 5 69 70 4 71 N 72 N 73 74 75 80							
Name and Location of Facility Inspected (Facility Data					
Name and Location of Facility Inspected (I POTW, also include POTW name and NP		Entry Time/Date 07/06/12 9:00am	Permit Effective Date				
City of Rigby WWTP	JEO permit numbery		01100112 9.00aiii	1-Aug-05			
3930 East 500 North		į	Exit Time/Date	Permit Expiration Date			
Rigby ID, 83442			07/06/12 12:30pm	31-Jul-10			
Name(s) of On-Site Representative(s)/Title			Other Facility Data (e.g.	, SIC, NAICS, and other			
Van Chenoweth and Tom Sessions, WWTP Operators			descriptive information)				
(208) 745-8111			Sanitary Services (SIC 4	1952, NAICS 221320)			
Name, Address of Responsible Official/Titl Keith Smith, Mayor	e/Phone and Fax Number						
158 West Fremont		Contacted					
Rigby, ID 83442		X Yes No					
(208) 745-8111		M					
Section C: Area	s Evaluated During Inspe	ction (Check on	ly those areas eva	luated)			
X Permit	X Self-Monitoring Program	Pretrea	itment	MS4			
X Records/Reports	Compliance Schedule	Pollutio	on Prevention				
X Facility Site Review	Laboratory	Storm '					
X Effluent/Receiving Waters X Operations & Maintenance Combined Sewer Overflow							
Flow Measurement Sludge Handling/Disposal Sanitary Sewer Overflow							
(Attach additional sh	Section D: Summary of eets of narrative and checklists, it			cessary)			
SEV Codes SE	EV Description			×			
		-					
		_					
See Attached Inpsection Report							
		_					
None (a) and Giventure (a) of immediate	A 222 21/05 22	/Dhana and Fan Na					
Name(s) and Signature(s) of Inspector(s)		/Phone and Fax Num	Date 6-Jul-12				
William Teuscher /, /		0 N. Skyline Dr Suite	0-Jul-12				
Signature of Management QA Reviewer	(208) 528-265 Agency/Office	/Phone and Fax Num	Date				
Manhin, FE 1060/5tate Office/208-373-0167/20976 To July 20							
EPA Form 3560-3 (Rev 1-06) Previous editions are obsolu	Ne	,		V V			

INSTRUCTIONS

Section A: National Data System Coding (I.e., PCS)

Column 1: Transaction Code: Use N, C, or D for New, Change, or Delete. All inspections will be 1274 unless there is an error in the data entered.

Columns 3-11: NPDES Permit No. Enter the facility's NPDES permit number - third character in permit number indicates permit type for U=unpermitted, G=general permit, etc... (Use the Remarks columns to record the State permit number, if necessary)

Columns 12-17: Inspection Date. Insert the date entry was made into the facility. Use the year/month/day format (e.g., 04/10/01 = October 01, 2004).

Column 18: Inspection Type*. Use one of the codes listed below to describe the type of inspection:

A	Performance Audit	U	IU Inspection with Pretrealment Audit	J	Prefreatment Compliance (Oversight)
В	Compliance Biomonitoring	X	Toxics Inspedion	_	Follows on to-fore second
C	Compliance Evaluation (non-sampling)	Ζ	Studge - Biosolids	@	Follow-up (enforcement)
D	Diagnostic	#	Combined Sewer Overflow-Sampling	,	Storm Water-Construction-Sampling
F	Pretreatment (Follow-up)	\$	Combined Sewer Overflow-Non-Sampling	1	oronn system-construction-psympting
G	Pretreatment (Audit)	+	Sanitary Sewer Overflow-Sampling	}	Storm Water-Construction-Non-Sampling
I	Industrial User (IU) Inspection	&	Sanitary Sewer Overflow-Non-Sampling		
J	Complaints	1	CAFO-Sampling	:	Storm Water-Non-Construction-Sampling
M	Multimedia	क्र	CAFO-Non-Sampling	_	Storm Water-Non-Construction-
N	Spill	2	IU Sampling Inspection		Non-Sampling
0	Compliance Evaluation (Oversight)	3	IU Non-Sampling Inspection	<	Storm Water-MS4-Sampling
Р	Pretreatment Compliance Inspection	4	IU Toxics Inspection		Storm Water-MS4-Non-Sampling
R	Reconnaissance	5	U Sampling Inspection with Pretreatment		Storm Water-MS4-Audit
S	Compliance Sampling	6	U Non-Sampling Inspection with Pretreatment	-	ALMIII TARIOLIMOA-VIOII
9	ownplian co oamping	7	U Toxics with Prefreatment		
		r	O LOVIDO ANTI LIGHIDANTICH		

Column 19: Inspector Code. Use one of the codes listed below to describe the lead agency in the inspection.

			•
B E J	State (Contractor) EPA (Contractor) Corps of Engineers Joint EPA/State Inspectors—EPA Lead Local Health Department (State) NEIC Inspectors	e	O— Other Inspectors, Federal/EPA (Specify in Remarks columns) P— Other Inspectors, State (Specify in Remarks columns) R— EPA Regional Inspector S— State Inspector T— Joint State/EPA Inspectors—State lead

Column 20: Facility Type. Use one of the codes below to describe the facility.

- 1 Municipal. Publicly Owned Treatment Works (POTWs) with 1987 Standard Industrial Code (SIC) 4952.
- 2 Industrial, Other than municipal, agricultural, and Federal facilities.
- 3 Agricultural. Facilities classified with 1987 SIC 0111 to 0971.
- 4 Federal. Facilities identified as Federal by the EPA Regional Office.
- 5 Oil & Gas. Facilities classified with 1987 SIC 1311 to 1389.

Columns 21-66: Remarks. These columns are reserved for remarks at the discretion of the Region.

Columne 67-69: Inspection Work Days. Estimate the total work effort (to the nearest 0.1 work day), up to 99.9 days, that were used to complete the inspection and submit a QA reviewed report of findings. This estimate includes the accumulative effort of all participating inspectors; any effort for laboratory analyses, testing, and remote sensing; and the billed payroll time for travel and pre and post inspection preparation. This estimate does not require detailed documentation.

Column 70: Facility Evaluation Rating. Use information gathered during the inspection (regardless of inspection type) to evaluate the quality of the facility self-monitoring program. Grade the program using a scale of 1 to 5 with a score of 5 being used for very reliable self-monitoring programs, 3 being satisfactory, and 1 being used for very unreliable programs.

Column 71: Biomonitoring Information. Enter D for static testing. Enter F for flow through testing. Enter N for no biomonitoring.

Column 72: Quality Assurance Data Inspection. Enter Q if the inspection was conducted as followup on quality assurance sample results. Enter N otherwise.

Columns 73-80: These columns are reserved for regionally defined information.

Section B: Facility Data

This section is self-explanatory except for "Other Facility Data," which may include new information not in the permit or PCS (e.g., new outfalls, names of receiving waters, new ownership, other updates to the record, SIC/NAICS Codes, Latitude/Longitude).

Section C: Areas Evaluated During Inspection